	r ID 57988 5, 2010 3:25:37 P.	M D	PLICE	TE IIIIIIII							Page 1
Item ID: Revision ID:	D4034-041			Accept				s	etup Star	1 12 8 10 10 1 0 1	
		nbly 54. rt Qty: 4.00 q'd Qty: 4.00	()	1881	Cust Item l Customer:	D:			Stop	1 18811186 81	
• •	Process Plan:QC:	My	Date: 10~4	-26 Tooling: SPC (Y/N):		ate:		R	Run Star Stop		
Sequence ID/ Work Center ID	Ope	ration cription		Set Up/ Run Hours	Draw	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision	Nbr									
D4034	Α										
	Weld	1 per dwg A/R S.S.	rod Batch: 1/1/					S	1 10/	24/27	Fx
Large Fab		Memo		0.00					3	7-1-1-0-7	
Large Fab		1- Assemble	e ribs to hoop and wel	d as per dwg DT9564							
		2- Weld bus	shing in rib and grind	weld flush as per dwg							
	QC9	- Inspect visual per	QSI004- Fusion Weld	is 0.00			(3)	8D (0	04,27		
QC Quality Control		Memo		0.00				(10 (0	.04,31		
120	QC5	- Inspect part comp	leteness to step on W/		Stroles			(15	>		
QC Quality Control		Memo		0.00	1004/27			(F)	<i>.</i>		- .

Dart	Aerospace	Ltd
W/O·		

W/O:	1		iES .								
DATE	STEP	PRO	CEDURE CH	IANGE	E	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No: PAR #		PAR #:	Fault Ca	tegory:	_ NCR:	Yes	No DQ	A :	Date:		
							C Closed: Date:				
NCR:		; V	ORK OR	DER NON-CONFORM	ANCE (VCR)				
DATE	STEP	Description of NC	Initial		tion B	: 0	Verific	ation	Approval	Approval	
		Section A	Chief Eng	Action Description Chief Eng		ign & Date	Secti	on C	Chief Eng	QC Inspector	
		. (·		
		1									
									!		
		1						i			
								,			
		:									
			,								

Work Order ID 57988

Monday, April 26, 2010 3:25:37 PM



Page 2

Item ID:

D4034-041

Accept

Setup Start

Stop



Item Name: Start Date:

Revision ID:

4/21/2010

Aft Upper Rib Assembly

Start Qty: 4.00 Reg'd Oty: 4.00 Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Required Date: 4/28/2010

Process Plan:

OC:

Date: Date: _____

Tooling:

SPC (Y/N):

Date:

Date:

Start Run



Stop

Sequence ID/ Work Center ID

130

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location:

Set Up/ Run Hours

0.00

0.00

Draw Rev.

Plan Code

Accept Otv

Reject Otv

Reject Insp. Number

Stamp

11.4

140

Quality Control

OC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10 04 128 Ty BS 10-4-28

Dart Aer	ospace	e Ltd							
W/O:	<u> </u>		· W	ORK ORDER CHANGES	3				
DATE	STEP	PF	ROCEDURE CH		Ву	Date	Date Qty Approval / Chief Eng / Prod Mgr		
			· 						
			! !					÷	
Part No:		PAR #:	Fault Cat	egory:	NCR: Ye	s No DQ	A:	Date:	
				on:					
NCR:		·	WORK OR	DER NON-CONFORMAN	CE (NC	CR)			
DATE	OTED	Description of NC		Corrective Action Section B		Vorifi	cation	A	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da	1& Sec	tion C	Approval Chief Eng	Approva QC Inspect
		<u>'</u>							
		İ							
								- 1	
		!							
{									•

Picklist Print

Monday, April 26, 2010 3:25:37 PM

Work Order ID: 57988

D4034-041

Parent Item Name: Comments:

Parent Item:

Aft Upper Rib Assembly

per dwg revA 10.03.15 verified by:EC

IPP RevA: new issue DD 09.11.23 verified by:EC

1124 1

Manufactured

Manufactured

IPP Rev:B as

Start Date: 4/21/2010

Otv

Issued

Required Date: 4/28/2010

Start Otv: 4.00

Required Otv: 4.00

Component Item ID/ Item Name

D4034-1

Replacement Mfg/ Item ID Purch

Rin **Primary** Item Location No Manufactured

Last Location Route Sea ID 100

Unit of Measure Each

Oty on Hand 10.0000

Loc Code

Remaining **Oty To Pick** 4.0000

Date Issued

Status

Page 1

Warehouse

Location

Main Warehouse WA

58037

No

No

10 Each

100

10

Loc Qty

5.0000

Loc Code

4.0000

Rib

D4034-3

Warehouse Location

WA

Main Warehouse

58099

100

Loc Qty

5 5

Each

0.0000

D4021-7



4.0000

5x B58039 6 St 10/04/26

Dart	Aerospace	Ltd
------	------------------	-----

W/O:			٧	VORK ORDER CHAN	NGES		<u></u>		
DATE STEP		PR	OCEDURE CH	IANGE	Ву	Da	te Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		į							
Part No	:	PAR #:	Fault Ca	tegory:	NCR: Ye	es No	DQA:	Date: _	1
Resolution: Disposition:									
NCR:			WORK OR	DER NON-CONFOR	MANCE (NO	CR)			
DATE	STEP	Description of NC		Section B	v	Verification	Approval	Approval	
	-	Section A	Initial Chief Eng	Action Descriptio	n Sig Da	n &	Section C	Chief Eng	QC Inspector
		·							
				·				,	
							÷		
					·			·	

Monday, April 26, 2010 3:25:37 PM

Work Order ID: 57988

Parent Item:

D4034-041

Parent Item Name:

Aft Upper Rib Assembly

Comments:

IPP RevA: new issue DD 09.11.23 verified by:EC

per dwg revA 10.03.15 verified by:EC

IPP Rev:B as

Start Date: 4/21/2010

Required Date: 4/28/2010

11 "

Start Qty: 4.00

Required Qty: 4.00

Component Item ID/ Item Name

D4021-9

Replacement Mfg/
Item ID Purch
Manufactured

Bin Primary
Item Location

Last Location Route Seq ID Unit of Qty on Measure Hand
Each 14.0000

on Remaining d Qty To Pick

ining Qty o Pick Issued Date Issued

Status

THE THE TEN SEED SEEDS WERE THE PROPERTY OF TH

Bushing

oc Qty Loc Code


WarehouseLoc OtyLocationImage: Comparison of the c

8 10 K


المرب

Dart Ae	rospace Lt	td						ı		
W/O:			WC	RK ORDER CHANGE	S		1			
DATE	STEP	PR	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approv QC Inspect				
		:								
Part No: PAR #:		PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:	Date: _			
	Reso	olution:	QA: N/C CI	A: N/C Closed: Date:						
NCR:	;		WORK ORDE	ER NON-CONFORMAN	ICE (NCR)	i			
DATE	STEP	Description of NC		В	Verification Approva		I Approva			
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspect		
		:								
								1		
		l								


H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



Dart Aerospace Ltd W/O: **WORK ORDER CHANGES Approval** DATE **Approval** STEP **PROCEDURE CHANGE** Ву Date Qtv Chief Eng / QC Inspector Prod Mgr Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: ____ Date: ____ Resolution: _____ Disposition: ____ QA: N/C Closed: ____ Date: ____ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B **Description of NC** Verification **STEP Approval** DATE **Approval** Initial **Action Description** Sign & Section A Section C Chief Eng QC Inspector Chief Eng Chief Eng Date



	rospace Lt					ļ					
W/O:	T		WC	ORK ORDER CHANGES	3						
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	/	Date Qty Approval Chief Eng / Prod Mgr QC				
		i									
Part No):	PAR #:	Fault Cate	gory:	NCR: Y	es N	o DQA	۱:	Date:		
Resolution:											
	Reso	lution:	Disposition	1:	QA: N/	Clos	sed:		Date: _		
NCR:	Reso			:: ER NON-CONFORMAN					Date:		
··			WORK ORDE		CE (N	ICR)					
NCR:	STEP		WORK ORDE	ER NON-CONFORMAN	CE (N			ation	Date:	Approv	
··		Description of NC	WORK ORDE	ER NON-CONFORMAN Corrective Action Section Action Description	CE (N	ICR)	Verific	ation	Approval	Approv	
··		Description of NC	WORK ORDE	ER NON-CONFORMAN Corrective Action Section Action Description	CE (N	ICR)	Verific	ation	Approval	Approv	
··		Description of NC	WORK ORDE	ER NON-CONFORMAN Corrective Action Section Action Description	CE (N	ICR)	Verific	ation	Approval	Approv	
··		Description of NC	WORK ORDE	ER NON-CONFORMAN Corrective Action Section Action Description	CE (N	ICR)	Verific	ation	Approval	Approva QC Inspec	



Dart /	Aeros	pace	Ltd
--------	-------	------	-----

W/O:			İ	V	VORK ORDER CHANG	ES						
DATE	STEP	. Р	ROC	EDURE CH	IANGE		Ву	D	ate	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			:									
	.		I								-	
			!									
								1		•		
			:							. •.1		
Part No	:	PAR #:		Fault Ca	tegory:	_ NCR	: Ye	s No	DQA:		_ Date: _	
	Res	Resolution: Disposition: QA			_ QA:	NC	Close	d:		Date:		
NCR:			W	ORK OR	DER NON-CONFORMA	NCE	(NC	CR)				
DATE	STEP	Description of NC			Corrective Action Section	on B		,	/erificat	ion	Approval	Approval
·	JILI	Section A		Initial Chief Eng	Action Description Chief Eng		Sigr Dat	1 & j	Section		Chief Eng	QC Inspector
				4								
					•		-					
					-							
-					. ;							
			1		,							